



Date: 6/24/2021

## Megger Test Report

	Stator	Rotor	Field Excitor	Rotor Excitor	PMG Field
<b>Arrive</b>	1 Meg	0.1	1 Meg	5 Meg	10 Meg
<b>Hot Dip</b>	10 Meg	1 Meg	10 Meg	15 Meg	50 Meg
<b>To Go</b>	15 Meg	3 Meg	20 Meg	30 Meg	100 Meg

Additional Information:

Rebuild SR4 B GD 1000 KW Cat Generator S/N G5B00782

Including: Clean, Dip, Paint, and Apply Red Seal to Windings Replace Front and Back Bearing

Replace some Covers on Junction Box