



Date: 6/24/2021

Megger Test Report

	Stator	Rotor	Field Excitor	Rotor Excitor	PMG Field
Arrive	0.2	0.1	3 Meg	20 Meg	10 Meg
Hot Dip	1 Meg	1 Meg	30 Meg	50 Meg	50 Meg
To Go	5 Meg	1 Meg	50 Meg	50 Meg	50 Meg

Additional Information:

Rebuild SR4 B GD 1000 KW Cat Generator S/N G5B00786

Including: Clean, Dip, Paint, and Apply Red Seal to Windings Replace Front and Back Bearing

Replace some Covers on Junction Box